

# NORTH WESTERN AGGREGATES PERMIT TO WORK

Site or quarry: *HEYWOOD MOOR*

Valid from: *22-3-16*

Plant or zone: *CRUSHING PLANT B*

Valid to: *23-3-16*

Contractor: *HALL AND PLATT*

Supervisor: *HUGH JONES*

Named operative(s): *TONY HALL*  
*GREGG PHILLIPS*

Work for which Permit to Work is required:

*INSPECTION AND MAINTENANCE OF AIR FILTERS*

Required safety precautions (including PPE):

*CLOSE DOWN AND LOCK-OFF ALL SUPPLIES*  
*HARD HATS, FACE MASKS, EYE PROTECTION AND GLOVES*  
*NB: MUST MARK AREA WITH 'CONTRACTOR AT WORK' SIGN*

Safety planning/risk assessment completed?

Yes

Pending

No

Approval of Permit to Work:

Signed *Scott Parker*

Date *14 March 2016*

NB: Only Site Manager or Quarry Manager to approve

Acceptance of Permit to Work:

Signed *A. J. Hall*

Date *18/3/16*

Completion of Work:

*ENSURE WASTE MATERIAL IS REMOVED!*

Signed

Date

Renewal of Permit to Work:

Signed

Approved until

Date

**IMPORTANT:** This Permit to Work **MUST** be shown to the Site Office on arrival and retained for inspection when required. Completed Permits to Work must be returned to the Site Office **BEFORE** leaving the site. If you need further information please call 01452 779 977 or 01339 452444.